FLOOD INSURANCE STUDY

CITY OF CENTER HILL, FLORIDA

SUMTER COUNTY

JANUARY 18, 1989

Federal Emergency Management Agency

COMMUNITY NUMBER 120615

NOTICE TO
FLOOD INSURANCE STUDY USERS

Communities participating in the National Flood Insurance Program have established repositories of flood hazard data for floodplain management and flood insurance purposes. This Flood Insurance Study may not contain all data available within the repository. It is advisable to contact the community repository for any additional data.

TABLE OF CONTENTS

		Page
1.0	INTRODUCTION	1
1.1	Purpose of Study	1
1.2	Authority and Acknowledgments	1
1.3	Coordination	2
2.0	AREA STUDIED	2
2.1	Scope of Study	2
2.2	Community Description	2
2.3	Principal Flood Problems	2
2.4	Flood Protection Measures	2
3.0	ENGINEERING METHODS	2
3.1	Hydrologic Analyses	4
3.2	Hydraulic Analyses	4
4.0	FLOODPLAIN MANAGEMENT APPLICATIONS	5
4.1	Floodplain Boundaries	5
4.2	Floodways	5
5.0	INSURANCE APPLICATION	5
6.0	FLOOD INSURANCE RATE MAP	6
7.0	OTHER STUDIES	6
8.0	LOCATION OF DATA	6
9.0	REFERENCES AND BIBLIOGRAPHY	7

TABLE OF CONTENTS (continued)

Page

FIGURE

Figure 1 - Vicinity Map 3

EXHIBITS

Flood Profile

Jumper Creek Panel 01P

Flood Insurance Rate Map

FLOOD INSURANCE STUDY

CITY OF CENTER HILL,
SUMTER COUNTY,
FLORIDA

1.0 INTRODUCTION

1.1 Purpose of Study

This Flood Insurance Study investigates the existence and severity of flood hazards in the City of Center Hill, Sumter County, Florida, and aids in the administration of the National Flood Insurance Act of 1968 and the Flood Disaster Protection Act of 1973. This study has developed flood risk data for various areas of the community that will be used to establish actuarial flood insurance rates and assist the community in its efforts to promote sound floodplain management. Minimum floodplain management requirements for participation in the National Flood Insurance Program are set forth in the Code of Federal Regulations at 44 CFR, 60.3.

In some states or communities, floodplain management criteria or regulations may exist that are more restrictive or comprehensive than the minimum Federal requirements. In such cases, the more restrictive criteria take precedence and the State (or other jurisdictional agency) will be able to explain them.

This Flood Insurance Study was prepared by compiling existing hydrologic and hydraulic technical and scientific data prepared by the Federal Emergency Management Agency (FEMA) for purposes of the National Flood Insurance Program and by other organizations for purposes other than the National Flood Insurance Program.

The data were identified as the best available at the time of compilation of this Flood Insurance Study and should depict the general conditions of the flooding sources with relative accuracy. FEMA performed a cursory review and accepted the data as valid for purposes of this Flood Insurance Study and the National Flood Insurance Program. However, if better information is known to exist or has been developed since the date of this report, the information should be immediately forwarded to the Natural and Technological Hazards Division, FEMA, Atlanta, Georgia, for consideration for revision of this study.

1.2 Authority and Acknowledgments

The sources of authority for this Flood Insurance Study are the National Flood Insurance Act of 1968 and the Flood Disaster Protection Act of 1973.

The hydrologic and hydraulic analyses for this study were obtained from the Flood Insurance Study for Sumter County, Florida, and the report titled "Flood Plain Information for the Panasoffkee-Jumper Creek Area, Sumter County, Florida" (References 1 and 2).

1.3 Coordination

On March 2, 1988, the results of this Flood Insurance Study were reviewed and accepted at a final coordination meeting attended by representatives of the community and FEMA.

2.0 AREA STUDIED

2.1 Scope of Study

This Flood Insurance Study covers the incorporated area of the City of Center Hill, Sumter County, Florida. The area of study is shown on the Vicinity Map (Figure 1).

The areas studied by detailed methods were selected based on the extent and validity of available existing hydrologic and hydraulic data.

Flooding caused by overflow of Jumper Creek was studied in detail.

Approximate methods of analysis were used to study all remaining areas of potential flood hazard that did not have detailed scientific or technical data available.

2.2 Community Description

The City of Center Hill is in eastern Sumter County, Florida, and is surrounded by the unincorporated areas of the county. Center Hill is approximately 35 miles west of the City of Orlando and 50 miles northeast of the City of Tampa. The community is served by the CSX railroad. The 1980 population of Center Hill was reported to be 751 (Reference 3).

2.3 Principal Flood Problems

Jumper Creek is the principal flooding source in the City of Center Hill.

2.4 Flood Protection Measures

Flood protection measures are not known to exist within the study area.

3.0 ENGINEERING METHODS

For the flooding sources studied in detail in the community, standard hydrologic and hydraulic study methods were used to determine the flood hazard data required for this study. Flood events of a magnitude that is expected to be equaled or exceeded once on the average during any 10-, 50-, 100-, or 500-year period (recurrence interval) have been selected as having special significance for floodplain management and for flood insurance rates. These events, commonly termed the 10-, 50-, 100-, and 500-year floods, have a 10-, 2-, 1-, and 0.2-percent chance, respectively, of being equaled or exceeded during any year. Although the recurrence interval represents the long-term average period between floods of a



FIGURE 1

FEDERAL EMERGENCY MANAGEMENT AGENCY

CITY OF CENTER HILL, FL
(SUMTER CO.)

APPROXIMATE SCALE

4 0 4 8 12 MILES

VICINITY MAP

specific magnitude, rare floods could occur at short intervals or even within the same year. The risk of experiencing a rare flood increases when periods greater than 1 year are considered. For example, the risk of having a flood that equals or exceeds the 100-year flood (1-percent chance of annual exceedence) in any 50-year period is approximately 40 percent (4 in 10), and, for any 90-year period, the risk increases to approximately 60 percent (6 in 10). The analyses reported herein reflect flooding potentials based on conditions existing in the community at the time of completion of this study. Maps and flood elevations will be amended periodically to reflect future changes.

3.1 Hydrologic Analyses

Hydrologic analyses were carried out to establish the peak discharge-frequency relationships for each riverine flooding source studied in detail affecting the community.

The hydrologic data for Jumper Creek were taken from the report titled "Flood Plain Information for the Panasoffkee-Jumper Creek Area, Sumter County, Florida" (Reference 2). The report presents flood profiles and hydrologic data for the mean annual 10-, 25-, 50-, 100-, and 500-year floods.

3.2 Hydraulic Analyses

Analyses of the hydraulic characteristics of flooding from the sources studied were carried out to provide estimates of the elevations of floods of the selected recurrence intervals.

Water-surface elevations of floods for the selected recurrence intervals for Jumper Creek were determined using the HEC-2 step-backwater computer program (Reference 4).

Flood boundaries in other locations in the community were determined by approximate methods using topographic maps (Reference 5).

Flood profiles were drawn showing the computed water-surface elevations for floods of the selected recurrence intervals. In cases where the 50- and 100-year flood elevations are close together, due to limitations of the profile scale, only the 100-year profile has been shown.

The hydraulic analyses for this study are based on the effects of unobstructed flow. The flood elevations shown on the profiles are thus considered valid only if hydraulic structures remain unobstructed, operate properly, and do not fail.

All elevations are referenced to the National Geodetic Vertical Datum of 1929 (NGVD).

4.0 FLOODPLAIN MANAGEMENT APPLICATIONS

The National Flood Insurance Program encourages State and local governments to adopt sound floodplain management programs. Therefore, each Flood Insurance Study provides 100-year flood elevations and delineations of the 100- and 500-year floodplain boundaries and 100-year floodway to assist communities in developing floodplain management measures.

4.1 Floodplain Boundaries

To provide a national standard without regional discrimination, the 1-percent annual chance (100-year) flood has been adopted by FEMA as the base flood for floodplain management purposes. The 0.2-percent annual chance (500-year) flood is employed to indicate additional areas of flood risk in the community. For each stream studied in detail, the 100- and 500-year floodplain boundaries have been delineated using the flood elevations determined at each cross section. Between cross sections, the boundaries were interpolated using topographic maps at a scale 1:24000 with a contour interval of 5 feet (Reference 5).

The 100-year floodplain boundaries are shown on the Flood Insurance Rate Map. On this map, the 100-year floodplain boundary corresponds to the boundary of the areas of special flood hazards (Zones A, AE, AH, AO, A99, V, and VE). Small areas within the floodplain boundaries may lie above the flood elevations but cannot be shown due to limitations of the map scale and/or lack of detailed topographic data.

4.2 Floodways

The floodway is the channel of a stream plus any adjacent floodplain areas that must be kept free of encroachment so that the 100-year flood can be carried without substantial increases in flood heights.

Floodways have not been shown or computed for this community. Along streams where floodways have not been computed, the community must ensure that the cumulative effect of development in the floodplain will not cause more than a 1.0-foot increase in the base flood elevations at any point within the community.

5.0 INSURANCE APPLICATION

For flood insurance rating purposes, flood insurance zone designations are assigned to a community based on the results of the engineering analyses. These zones are as follows:

Zone A

Zone A is the flood insurance rate zone that corresponds to the 100-year floodplains that are determined in the Flood Insurance Study by approximate methods. Because detailed hydraulic analyses are not performed for such areas, no base flood elevations or depths are shown within this zone.

Zone AE

Zone AE is the flood insurance rate zone that corresponds to the 100-year floodplains that are determined in the Flood Insurance Study by detailed methods. Whole-foot base flood elevations derived from the detailed hydraulic analyses are shown at selected intervals within this zone.

Zone X

Zone X is the flood insurance rate zone that corresponds to areas outside the 100-year floodplain, areas of 100-year flooding where average depths are less than 1 foot, areas of 100-year flooding where the contributing drainage area is less than 1 square mile, and areas protected from the 100-year flood by levees. No base flood elevations or depths are shown within this zone.

6.0 FLOOD INSURANCE RATE MAP

The Flood Insurance Rate Map is designed for flood insurance and floodplain management applications.

For flood insurance applications, the map designates flood insurance rate zones as described in Section 5.0 and, in the 100-year floodplains that were studied by detailed methods, shows selected whole-foot base flood elevations or average depths. Insurance agents use the zones and base flood elevations in conjunction with information on structures and their contents to assign premium rates for flood insurance policies.

For floodplain management applications, the map shows by tints, screens, and symbols the 100- and 500-year floodplains, the floodways, and the locations of selected cross sections used in the hydraulic analyses and floodway computations.

7.0 OTHER STUDIES

The Flood Insurance Study published for Sumter County (Reference 1) is in agreement with this study.

8.0 LOCATION OF DATA

Information concerning the pertinent data used in the preparation of this study can be obtained by contacting the Natural and Technological Hazards Division, FEMA, 1371 Peachtree Street, NE., Suite 736, Atlanta, Georgia 30309.

9.0 REFERENCES AND BIBLIOGRAPHY

1. Federal Emergency Management Agency, Flood Insurance Study, Sumter County, Unincorporated Areas, Florida, March 1982.

2. Southwest Florida Water Management District, Flood Plain Information for the Panasoffkee-Jumper Creek Area, Sumter County, Florida, August 1978.

3. U.S. Department of Commerce, Bureau of the Census, 1980 Census of Population, Number of Inhabitants, Florida, Washington, D.C., February 1982.

4. U.S. Army Corps of Engineers, Hydrologic Engineering Center, HEC-2 Water-Surface Profiles, Generalized Computer Program, Davis, California, April 1984.

5. U.S. Geological Survey, 7.5 Minute Series Topographic Maps, Scale 1:24000, Contour Interval 5 Feet: Bushnell, Florida, 1958; Center Hill, Florida, 1969.

FLOOD PROFILES

JUMPER CREEK

FEDERAL EMERGENCY MANAGEMENT AGENCY

CITY OF CENTER HILL, FL
(SUMTER CO.)

01P